


Automatic charger

Cut out
BLUE
2.25

CA 3140E Source 40ma.
S2800D - 15ma trigger



OP-AMP failed replaced with

NS 741